METHOD FOR CONTROLLING A BURNISH CYCLE TO MINIMIZE CYCLE TIME

ABSTRACT

A method for controlling a burnish cycle to minimize cycle time is disclosed.

MR sensor resistance measurements are used to monitor interference with the recording surface and when clearance is not detected, steps are taken to fine tune the interference signal.